

**WARRANTY:**

The DLA warrants DLA Rebuilt engines to be free of defects at the time of purchase. All DLA Rebuilt engines have a one **(1) year**, warranty on Parts and a lifetime warranty on labor from the date of purchase, when purchased from a GOLDEN SKIES R/C AIRCRAFT, Inc... The DLA Rebuilt warranty is granted to the original engine purchaser only, and is not transferable or assignable. During the warranty period, GOLDEN SKIES R/C AIRCRAFT, Inc. will, at the discretion of GOLDEN SKIES R/C AIRCRAFT, Inc., and/or AeroScott, Inc. Engine Repair, Service, replace engine parts that do not meet original factory specifications. All DLA engines must be marked with a factory Serial Number for the warranty to apply.

Golden Skies R/C Aircraft, Inc. does not honor the warranty on any other DLA Rebuilt engine(s) that were rebuilt by any other entity other than Golden Skies R/C or AeroScott Engines Service.

All DLA Rebuilt Engines are rebuilt by AeroScott, Inc. and will be rebuilt with all new, DLA factory provided parts. If the customer wants the rebuilt engine test run and a test run data sheet provided, a charge of \$50.00 must be paid to AeroScott, Inc. at the time of Purchase. All new prop-bolts will be provided for all rebuilt engines. Sparkplug may or may not be provided in the rebuilt engine kit. CDI will be replaced with new CDI as determined by AeroScott, Inc.

Bowman Rings may be added to the rebuilt engine upon request of the customer for the cost of the rings and a \$35.00 service charge. Bowman rings must be requested at the time of the rebuild.

**Rebuilt Warranty Registration** must occur within seven (7) days of the original purchase date. The original purchaser must register the DLA engine with Golden Skies R/C Aircraft, and provide the following:

- Date and place of Purchase, copy of Sales Receipt.
- Engine Serial Number.
- Name, address, phone and E-mail address of Original Purchaser.
  - The purchaser assumes the responsibility of maintaining a current email address with GOLDEN SKIES R/C AIRCRAFT, Inc.

The Warranty does not cover any of the following:

- Damage caused by:
  - Improper Handling.
  - Improper Operation.
  - Disassembly, in any way, of the Engine or Carburetor System.
    - Disassembly will invalidate the warranty.
  - Engine or Carburetor Modifications.
  - Damage caused by trauma, impact or crashes
  - Damage caused by use of improper fuels or oils, or mixtures thereof.
    - 87 or 89 Octane, unleaded gasoline is all that is allowed.
    - Ethanol Content of gas in excess of 15% will void the warranty
  - Interior Rubber Carburetor parts are normal "Wear and Tear" parts.
 

**NOTE:** Gas / Alcohol mixtures or Alcohol additives to the gas are known to accelerate deterioration of carburetor rubber parts.
  - Damage caused by Fuel or Gas Additives other than what is described in the DLA-GS R/C Operations Manual.



- Ethanol Content of Gas in excess of 15% will void the warranty
- Damage cause by improper ignition battery selection.
- Damage incurred during transit to or from the repair facility.
- Stripped or cross-threading bolts or spark-plug(s).
- Damage as a result of improper electrical wiring connections.
- Damage caused by overheating the engine.
- Tune-ups, including the sparkplug(s).
- Any other use of the DLA engine(s) for purposes other than powering a Model Aircraft will void the warranty.
- Shipping Charges to and return from the GS R/C service center are not covered.

### HOW TO OBTAIN WARRANTY SERVICE:

1. Contact GS R/C for an authorization warranty return case-number.
2. Return the following to GS R/C:
  - a. Engine
  - b. Muffler(s)
  - c. Sparkplug(s)
  - d. Ignition
3. Ship the items listed in #2 above to: (GS R/C is not responsible for shipment loss or shipment damage.)  
AeroScott, Inc  
Service Dept.  
10820 S. Central Ave  
Ontario, CA 91762
4. Insure the Engine for the purchase Price or as follows whichever is more:
 

a. DLA 32cc Engine	\$ 300.00
b. DLA 58cc Engine	\$ 400.00
c. DLA 64cc Engine	\$ 550.00
d. DLA 116cc Engine	\$ 700.00
e. DLA 128 Engine	\$ 1,399.00
f. DLA 180 Engine	\$ 1,189.00
g. DLA 232 Engine	\$ 1,850.00
5. Include a typed and signed explanation of the engines problem(s)
  - a. Use the GS R/C – DLA Service Request Form (See Website for Form)
6. The AeroScott, Inc. Service Department will respond with an estimate for labor charges.
7. Damaged parts or parts that do not meet factory specification will not be return to the sender.
8. Provide full information: Name, address, phone #, email address & Credit Card